

Factsheet

Seahaven Pools

Commercial, Residential and Industrial

Project Title

Seahaven Pools

Location

Harbour City, NCD, PNG

Client

Seahaven Ltd

Project Type

Residential Swimming Pool

Year Completed

2010



Project Description

Client requested a structural report plus quotation including recommended contractor to repair their swimming pool. The pool was leaking and the Client could not determine the cause and the technicality of fixing it.

Client also involved a Pool Doctor to obtain further information on diagnosis to date and future approach.

Kramer Ausenco was commissioned by Seahaven Limited to carry out an inspection of a swimming pool located at Seahaven Apartments on Brampton Street, Port Moresby. The report covered the inspection and findings together with recommendations on possible repairs to allow reuse of the pool.

Report was completed and provided to Client on time as expected.

Total Floor Area

200 sqm

Project Role

- Civil Engineers

