

Factsheet

Windward Remedial

Commercial, Residential and Industrial

Project Title

Windward Remedial

Location

Port Moresby, PNG

Client

Steamships

Project Type

Commercial & Residential

Year Completed

2013



Project Description

Kramer Ausenco's structural expertise was used in this project. We were to monitor and oversee the thorough removal of existing patchwork and the consequent reinstatement of every structural wall, column & beam which was affected by the chipping and chasing. Regular inspections were carried out to ensure compliance with set standards. Upon completion, a report was written stating the scope of the job and certifying the job as complete and appropriate.

Project Role

- Structural Engineering